Selecting the Right Gladhand to Help Prevent Corrosion

Anodized – Virtually no corrosion on the body

Powder Coated – Corrosion has begun where the coating has chipped

The Connector Plate



Stainless Steel Connector Plate



Powder Coated Steel Connector Plate

The Detent Plate and Rivets

Connector Dimple with Wear

Heavy Abrasion



Corroded detent plate and rivets

- F /" !#+$(/ " !//("0 $$/0! &"2(#!/ ". &": / !"#$!+10 && +5/"2& !/0!+ $6"
- A#!0)". &"(" ."!/$ + $"*)/$"0 ,2(+$'"#$%",$0 ,2(+$'"'(#%)#$% 9"!)+ "+ "#" ,&/" +'$"!)/4"$//%"! ":/" &/2(#0/%6"
- ;$"+ - 2 &!#$!"2(#0/"! "*#!0)". &"0 && + $"+ "!)/"+$!/&+ &"0#5+!4" ."!)/"'(#%)#$%6"?."0 && + $": ,+(%,2":/1 '+$ "! "0)+2"#*#49"+!"*+(("/$!/&"!)/"#+&(+$/" 4 !/ - 6"