
Literius veet eeg — Asimintelineiles

Jls2, 2009

MARTIN FORSYTH DIRECTOR OF WARRANTY HYUNDAI TRANSLEAD 8880 RIO SAN DIEGO DR, SUITE 600 SAN DIEGO CA 92108 NVS-215dgl 09V-247

SUBJECT: QUICK RELEASE VALVES/HALDEX/MERITOR WABCO

DEAR MR. FORSYTH:

Thisleters restricted the Hodiai Takead in the Natal High any Taffic Safety Adinair (NHTSA) for a sign that the Hodis desibed below thich a afetyer and the side of the Hodis and the Hodis desibed below that the Hodis and the H

Fedeal law

Pleas eie the filing if nintes hatite fist yeeds ashis if nini she ig nade a wilable the place of state in the indicate of the place of the indicate of the in

Makes/Models/Model Years: HYUNDAI TRANSLEAD/CHASSIS/2008 HYUNDAI TRANSLEAD/CONVERTER DOLLY TRAILER/2008

NHTSA Campaign Number: 09V-247

Mfg's Report Date: Ja 17, 2009

Components: SERVICE BRAKES, AIR: SUPPLY: QUICK RELEASE VALVE

Potential Number of Units Affected: 572

Summary:

HYUNDAI TRANSLEAD IS RECALLING 572 CONVERTER DOLLY TRAILERS MANUFACTURED FOR FEDEX GROUND AND EQUIPPED WITH CERTAIN HALDEX QUICK RELEASE VALVES (QRV). THE RUBBER DIAPHRAGM INSIDE THE QRV MAY EXPERIENCE DELAMINATION RESULTING IN SIGNIFICANT LEVELS OF AIR PRESSURE LEAKAGE PAST AND/OR THROUGH THE DIAPHRAGM, OR THE DEVELOPMENT OF A BUBBLE IN THE DIAPHRAGM WHICH MAY TRAP AIR PRESSURE IN THE VALVE AND NOT ALLOW THE SERVICE BRAKES TO RELEASE.

Consequence:

MALFUNCTION OF THE AIR BRAKE SYSTEM COULD RESULT IN A VEHICLE CRASH.

Ynchectschise call is be Delia Lexisony be eached by he at 202-366-9525, the panil at RMD.ODI@dtgw. . We lke find the ig its structure of the panil at the control of the panil is the panil of th

Sineely

Gege H. Pen

Chief, Recall Mangent Disso Office 6 Defect Insignio

Eficeen